Scope of	Work for Property Loc	cated at	:	<u>2049</u>	South 15th Place	
	Property is: Single Far	nily 🗹	Duplex		Other 🗆	
Date:	1/22/2014					
ake no respo		after the in	spection da	te, or for	ty of Milwaukee, the Redevelopment omissions through error or oversight. k Grant or HOME programs.	
Exterior	Condition Report					
_ocation Site	Required Work Landscaping	n/a ✓	Yes 🗌	Note/C Self He	Comments Ip	\$ Cost
	Steps/Handrails	n/a ✓	Yes 🗌			\$
	Service walks	n/a 🗌	Yes 🗸	assum	ed-snow covered	\$ 600.00
	Fencing	n/a ☑	Yes			\$
	Parking	n/a ✓	Yes 🗌			\$
	Retaining walls	n/a ✓	Yes 🗌			\$
	Other	n/a	Yes \square			\$
	Other	n/a □	Yes 🗌			\$
Garage	Singles: repair	n/a 🗌	Yes 🗌			\$
	Shingles: Roof over existing	n/a 🗌	Yes 🗌			\$
	Shingles:Tear off & re-roof	n/a 🗌	Yes 🗌			\$
	Gutters/downspouts	n/a	Yes 🗌			\$
	Flashing	n/a 🗌	Yes 🗌			\$
	Eaves	n/a 🗌	Yes 🗌			\$
	Siding	n/a	Yes 🗌			\$
	Doors	n/a 🗌	Yes 🗌			\$
	Windows	n/a 🗌	Yes 🗌			\$
	Slab	n/a	Yes 🗌			\$
	Paint	n/a	Yes 🗌			\$
	Electrical	n/a	Yes 🗌			\$
	Other	n/a 🗌	Yes 🗌			\$
Porches	Roof	n/a ✓	Yes 🗌			\$
	Deck-upper	n/a ☑	Yes 🗌			\$
	Decklower	n/a	Yes 🗌			\$
	Steps/handrails	n/a	Yes ✓			\$ 450.00
	Ceiling	n/a ☑	Yes 🗌			\$
	Guardrails	n/a ☑	Yes 🗌			\$
	Structural	n/a ☑	Yes 🗌			\$
	Paint	n/a ✓	Yes 🗌			\$

n/a 🗌 Yes 🗹 **permit**

Other

85.00

\$

House

Chimney	n/a ☐ Yes ☑	\$ 400.00
Shingles: repair	n/a ☑ Yes □	\$
Shingles: Roof over existing	n/a ☑ Yes □	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 10,000.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 1,008.00
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a 🗌 Yes 🗹 fascia & soffit	\$ 500.00
Siding	n/a ☑ Yes 🗌	\$
Storm Doors	n/a ☑ Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 1,050.00
Storm Windows	n/a ☑ Yes □	\$
Prime ("main") Windows	n/a ☑ Yes 🗌	\$
Paint	n/a Yes previously painted surfaces	\$ 950.00
Foundation	n/a ☑ Yes □	\$
Electrical	n/a ☑ Yes □	\$
Other	n/a 🗌 Yes 🗹 structural	\$ 9,500.00
Other	n/a 🗌 Yes 🗹 window screens	\$ 400.00
Other	n/a 🗌 Yes 🗹 misc window trim	\$ 500.00
Other	n/a 🗌 Yes 🗍	\$

Exterior: Estimated Cost:*

\$

25,443.00

 $[\]ensuremath{^{\star}} \text{average}$ contracted cost. Actual costs may vary. Self help will reduce the amount.

	Unit: Entire unit (single family) Upper unit of duplex Required Work	✓ □				Lower unit of duplex Other	
Heating	Repair/replace boiler	n/a	V	Yes			\$
	Repair radiation	n/a	V	Yes			\$
	Repair/replace furnace	n/a		Yes	V	service	\$ 350.00
	Repair ductwork	n/a	V	Yes	V		\$ 400.00
	Replace thermostat	n/a	V	Yes			\$
	Repair/replace grilles	n/a	V	Yes			\$
- 1	Tune boiler/furn. insp ht exchang	n/a	V	Yes			\$
Electrical	Repair/replace receptacles	n/a	V	Yes			\$ 250.00
	Repair/replace switches	n/a		Yes	V		\$ 250.00
	Repair/replace fixtures	n/a		Yes	V		\$ 400.00
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a	V	Yes			\$
	Other	n/a		Yes	✓	permits	\$ 85.00
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	V	Yes			\$
	Repair/replace kitchen sink fauce	n/a	V	Yes			\$
	Repair/replace tub	n/a	V	Yes			\$
	Repair/replace tub faucet	n/a	V	Yes			\$
	Repair/replace toilet	n/a	V	Yes			\$
	Repair/replace lavatory	n/a	V	Yes			\$
	Repair/replace lavatory faucet	n/a	~	Yes			\$
	Repair/replace wash tub	n/a	V	Yes			\$
	Repair/replace wash tub faucet	n/a	V	Yes			\$
	Unclog piping:	n/a	V	Yes			\$
	Repair drain/waste/vent piping	n/a	√	Yes			\$
	Other	n/a		Yes	V	permits	\$ 85.00
	Repair/replace water heater	n/a		Yes	V	service	\$ 350.00
	Other	n/a		Yes	√	repair or disconnect basement bathroom	\$ 1,600.00

n/a Yes plumbing per code

Interior Condition Report

Other

Windows												
	Replace broken glass	n/a	V	Yes			\$					
	Repair or replace sash	n/a	V	Yes			\$					
Doors												
	Repair or replace doors	n/a	7	Yes			\$					
	Repair or repl. locks/latches	n/a	V	Yes		Self Help	\$					
Walls/Ceilin	<u>-</u>	,		.,			•	0.000.00				
	Repair or repl. @ defective	n/a		Yes	1		\$	2,200.00				
Paint	Repair or repl. @ defective	n/a		Yes	✓		\$	1,490.00				
Fire Safety												
•	Install smoke/CO alarm:bsmt.	n/a		Yes	V	Self Help	\$	55.00				
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	165.00				
	Install smoke/CO alarm: 2nd flr.	. n/a	V	Yes		Self Help	\$					
Handrails	Repair/replace defective	n/a	V	Yes		Self Help	\$					
Stairs	Repair defective	n/a		Yes	7		\$	1,064.00				
Floors	· ·											
	Repair defective	n/a		Yes	1		\$	2,600.00				
Other		n/a		Yes	V	seal chimney	\$	100.00				
		n/a		Yes			\$					
		n/a		Yes			\$					
		n/a		Yes			\$					
						Interior: Estimated Cost:	\$	11,444.00				
						Total Exterior and Interior Cost:*	\$	36,887.00				
						*average contracted east. Actual costs may year. Salf help will reduce	o contracted each. Actual costs may yarry. Solf help will reduce the amount					

Inspected by: Tom Frank Date: 1/21/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.